
General technical information for turning

The functions of each part of turning tools

The names of each part of turning tools



Effects of rake angle

Larger rake angle makes cutting edge sharper, reduces resistant forces of chip flow, diminishes friction and prevent deformation, leading to smaller cutting forces and cutting power, lower cutting temperature, less abrasion and higher surface quality. However, too large rake angle would reduce the rigidity and strength of tool. Heat can't be diffused easily. Serious breakage and abrasion on tool would occur, reducing tool life. Please choose rake angle according to machining conditions.

Value selection	Situations
Small rake angle	When machining brittle and hard materials When roughing and intermittent cutting
Big rake angle	When machining plastic or soft materials When finishing

Effects of clearance angle

The main function of clearance angle is to reduce the friction between the clearance face of tool and the surface of workpiece. When the rake angle is fixed, larger clearance angle can increase the sharpness of cutting edge, reduce cutting forces and friction, and then achieve higher surface quality. However, if clearance angle is too large, the strength of cutting edge would decrease. Also, heat can't be diffused easily and serious abrasion would occur, reducing tool life.


The principle of choosing clearance angle: Choose small clearance angle if friction is not serious.

Effects of inclined angle

Positive or negative inclined angle determines the direction of chip flow, and also affects the strength and impact resistance of insert nose.

◆As diagram (1) shows, when the inclined angle is negative, namely nose is in the lowest point as apposed to the bottom of tool, chips flow to the machined surface of workpiece.


Value Selection	Situations
Small clearance angle	In order to increase nose strength when roughingWhen machining brittle and hard materials
Large clearance angle	In order to reduce friction when finishingWhen machining materials easy to be hardened



General Technical Information for Turning TURNING

General technical information for turning -


- ◆ As diagram (2) shows, when inclined angle is positive, namely the nose is in the highest point as apposed to the bottom of the tool, chips flow to the areas of workpiece surface that haven't been machined.
- ♦ The change of inclined angle also affects insert nose strength and impact resistance. When the inclined angle is negative, the nose is in the lowest point of cutting edge. When the cutting edge enters the workpiece, the contacting point is on the cutting edge or rake face, protecting the nose from impact and increase the strength of the nose. Normally, negative inclined angle should be chosen for tools with big rake angle. This can not only increase nose strength, but also prevent the impact of entry.



5 Effects of approach angle

Reduced approaching angle increases the strength of tools and enable heat to diffuse easily, improving surface quality. This is because when the approach angle is small, cutting edge width is large, and then the unit width of cutting edge bears less cutting force. Meanwhile, tool life can be improved.

Normally, select 90° approach angle for turning of slender and step shaft; select 45° approach angle for external turning, end surface machining and chamfering. When approach angle is larger, radial force is reduced, cutting is stable, cutting thickness is increased, and chip breaking is excellent.



Value selection	Situations
Small approach angle	For those materials with high intensity, high hardness and hardened layer on the surface
Big approach angle	When rigidity of the machine is not enough

6 Effects of secondary declination angle

Minor angle is the main angle that can affect surface quality, and it can also affect tool strength. If the approach angle is too small, the friction between the secondary flank and machined surface of workpiece will increase, causing vibration.

The principle of selecting minor angle: Select small minor angle when roughing or when the friction is unaffected and there is no vibration. Select large minor angle when finishing.

7 Nose radius

Nose radius significantly affects nose strength and surface quality.


Large nose radius means higher cutting edge strength, and the abrasion on the rake face and clearance face can be reduced to some extent. However, if the nose radius is too large, radial force will increase, and vibration is easy to occur, affecting machining precision and surface quality.

Value selection	Situations
Small nose radius	●Finishing at small cutting depth ●Machining parts such as slender shaft ●When the rigidity of the machine is not enough
Large nose radius	 ◆When roughing ◆When machining hard materials (intermittent cutting) ◆When the rigidity of the machine is not enough

General technical information for turning

Calculation method of turning parameters

Calculation of cutting speed



$$V_C = \frac{\pi \times D \times n}{1000}$$
 (m/min)

In the formula: Vc: Cutting speed (m/min)


n: Rotating speed of spindle (rev/min)

D: Diameter of workpiece (mm)

For example: When the rotating speed is 280rev/min and the diameter of workpiece is 150mm, the cutting speed should be:

$$V_c = \frac{\pi \times D \times n}{1000}$$
 (m/min) =132(m/min)

Calculation of feed rate



$$f = \frac{l}{n} (mm/rev)$$

In the formula: f: Feed rate per rotation (mm/rev)

I: Cutting length per minute (mm/min)

n: Rotating speed of spindle (rev/min)

For example: When the rotating speed of main axle is 500rev/min, and the cutting length per minute is 100mm/ min, the feed rate per rotation should be:

$$f = \frac{l}{n} = \frac{100}{500} = 0.2 (mm/rev)$$

General technical information for turning -

3 Cutting time calculation of external and internal turning

$$T = \frac{l}{f \times n} \ (min)$$

In the formula: T: Cutting time (min)


I: Length of machined areas (mm)

f: Feed rate (mm/rev)

n: Rotating speed of main axle (rev/min)

For example: When the rotating speed of main axle is 250rev/min, and the feed rate is 0.2mm/rev, the time needed for a cutting length of 150mm should be:

$$T = \frac{l}{f \times n} = \frac{150}{0.2 \times 250} = 3$$
(min)



Time calculation for end surface turning (constant linear speed)


$$T = \frac{\pi \times (a^2 - b^2)}{4000 \times Vc \times f} \quad (min)$$

In the formula: T: Cutting time (min)

Vc: Cutting speed (m/min)

f: Feed rate (mm/rev)

For end surface without hole, b=0, the formula is still valid.



Theoretical value calculation of machined surface roughness

$$R = \frac{f^2}{8r_c} \times 1000 \, (\mu m)$$


In the formula: R: Theoretical roughness value of machined surface

f: Feed rate (mm/rev)

rc: Nose radius (mm)

For example: When the feed rate is 0.2mm/rev, and the nose radius is 0.4mm, the theoretical roughness value of machined surface should be:

$$R = \frac{f^2}{8r_c} \times 1000 = \frac{0.2^2}{8 \times 0.4} \times 1000 = 12.5 (\mu m)$$




General technical information for turning

Effect of three main turning parameters on machining

Effects of three main parameters

Normally, short machining time, long tool life and high machining precision are expected in machining, so the material quality, hardness, and shape of the workpiece, and properties of machine should be fully considered, and then we can select suitable tools and adopt high-efficiency cutting parameters, namely three parameters.



Cutting speed (Vc)

When the workpiece is rotating on the machine, the number of its rotation per minute is defined as Rotating speed of main axle (n). Because of its rotation, the cutting speed measured on the contacting point of diameter is defined as linear speed, m/min. Normally, linear speed is considered to measure the effect of cutting speed on machining.

Effect of cutting speed

Cutting speed has significant effect on tool life. When the cutting speed is increased, cutting temperature will increase and tool life will be shortened. Cutting speed varies according to the different types and hardness of workpiece. The below conclusions are reached after many cutting experiments:

- (1) Normally tool life would be reduced to half when the cutting speed is increased by 20%. Tool life would be 20% of the original life if the cutting speed is raised by 50%.
- (2) Low speed (20-40m/min) cutting could easily cause vibration and shorten tool life.

Feed rate (fn)

Feed rate is defined as the moving distance of tool after workpiece rotates for one circle, measured by mm/ rotation.

Effect of feed rate

Feed rate is a key factor that determines surface quality. Meanwhile it also affect the range of chip forming and the thickness of chips during machining.

In term of the effect on tool life, small feed rate leads to serious abrasion on clearance face, greatly reducing tool life.

Cutting depth (ap)

Cutting depth is defined as the difference between machined surface and unmachined surface, measured by mm. It is half the difference value between the original diameter and machined diameter.

Effect of cutting depth

Cutting depth should be determined by the machining allowance and shape of workpiece, power and rigidity of machine, and tool rigidity.

The change of cutting depth has little effect on tool life. If the cutting depth is too low, the cutting nose only scrapes the hardened layer on the workpiece surface, reducing tool life. When there is hardened oxide layer on workpiece surface, higher cutting depth should be adopted within the possible range of machine's power to avoid cutting nose just cutting the hardened layer of workpiece.

General

Comparison table for turning insert chipbreaker

Negative inserts

CCCCT SANDVIK KORLOY TaeguTec WALTER SECO MTSUBISHI SUMITOMO KENNAMETAL DIJUET	HITACHI TUNGALOY KYOCERA VALANTTE	ZF DP%, GP, F1 XP-T, XF	HQ, CQ F2(2B),	XQ, XS	.W WF	F3, F4(8A), PG, CJ, M2(2C), M3 GS, PS M4, M5(5B), HS, PT M6, M7, 55,	WE	RH, GT	R3, R4, R6(9A)
CCC.CT SANDVIK KORLOY TaeguTec WALTER SECO MITSUBISHI SUMITOMO KENNAMETAL DIJUET	TUNGALC		NS, 27 TSF, AS, 1	17	AFW, AS FW, SW	NM, ZM TM, DM 37, AM 33, 38		Ŧ	
CCC.CT SANDVIK KORLOY Taegurec WALTER SECO MITSUBISH SUMITOMO KENNAMETAL		Ħ	B, B,			CT AY AE AH		>-	TE, UE HX, HE
CCC.CT SANDVIK KORLOY TaeguTec WALTER SECO MITSUBISHI DF PF HF FA FF1 PK% FH, FY XF HF FG MP3, FV5 FF2 FP, FS NM WL HW WS NF3 NF4 FP, FS PM WL HW WS NF NMF3 NMF3 NMP NM WM HM SM MP5 MR NM NM LRSingle-side) PR, HM HM RT NM6, RP5 MR RP RP HDR PR HR HY, HT NM6 RA, R6 HM, HL HDR PR HR HY, HT NRF RA, R6 HM, HL			PF, UR UA, UT			B B		UD, GG	On .
CCC.CT SANDVIK KORLOY TaeguTec WALTER SECO MITSUBISHI DF PF HF FA FF1 PK% FH, FY XF HF FG MP3, FV5 FF2 FP, FS NM WL HW WS NF3 NF4 FP, FS PM WL HW WS NF NMF3 NMF3 NMP NM WM HM SM MP5 MR NM NM LRSingle-side) PR, HM HM RT NM6, RP5 MR RP RP HDR PR HR HY, HT NM6 RA, R6 HM, HL HDR PR HR HY, HT NRF RA, R6 HM, HL	KENNAMETA	Æ	LF, FN		FW	₽ Ä	MW	X X	MR, RM
CCC.CT SANDVIK KORLOY TaeguTec WALTER SECO DF HU FA FP5 FF1 LC HF FG MP3, FV5 MF2 FX XF FF4 FF2 FF2 NM- HW WW NF3, NF4 MF3 MF2 FX FF FG MF3, NF4 MF3 MF2 MF3 NM- HW HA FT MF3 MF3 MF3 MF3 NM- HM SM MF3 MF3 MF3 MF3 NMM MM HM SM MF3 MF3 MF3 NMM NMM MM NMM5 MF3 MF3 MF4 NMM NMM NMM NMM6 NMM7 NMM6 MF3 RA, R6 HDR PR HR HY, HT NR RA, R6 RA, R6 HDR PR HR HY, HT MR RA, R6 RA,			FE, SU, LU, SX, SE		LUW	OB NY OB	GUW	MU, MX ME, UZ	
CCC.CT SANDVIK KORLOY TaeguTec WALTER SECO DF HU FA FP5 FF1 LC HF FG MP3, FV5 MF2 FX XF FF4 FF2 FF2 NM- HW WW NF3, NF4 MF3 MF2 FX FF FG MF3, NF4 MF3 MF2 MF3 NM- HW HA FT MF3 MF3 MF3 MF3 NM- HM SM MF3 MF3 MF3 MF3 NMM MM HM SM MF3 MF3 MF3 NMM NMM MM NMM5 MF3 MF3 MF4 NMM NMM NMM NMM6 NMM7 NMM6 MF3 RA, R6 HDR PR HR HY, HT NR RA, R6 RA, R6 HDR PR HR HY, HT MR RA, R6 RA,	MITSUBISHI	PK** FH, FY FP, FS	LP, C SA, SH	SY	SW	M W W	M√	RP HD	
SF HU FX FF FF FM NF3, NWX NWX NWY NF1 NW6, DR(boubeside) XMR HR HY HY HT HY HY HT HY HT HY HT HY HT HY HT NF1		FF1 FF2	MF2		W-MF2	MF3 MF5 M3	W-M6 W-M3		R5, R56 R4, R6 R7, PR9
	WALTER	FP5	MP3, FV5 NF3, NF4		ΗN	MF3 MV5	W _Z	NM6, RP5 NM9, RP7	NR6 NRF
	TaeguTec	Ą X	E FG	PC	WS	PC SM MT	M	RT	RX, HD HY, HT
	KORLOY	HU	生	生	МН	H H H			光 . 王
	SANDVIK	QF	g X		WF	M W X	WWX WW	PR, HM XMR	Q T I
Machining range For extra finishing (Soft steel) For finishing (Wiper) For semifinishing (Wiper) For semifinishing (Wiper) For semifinishing finishing finishing roughing roughing roughing	ZCC.CT		A X	SF		M M X		LR(Single-side) DR(Double-side)	HDR
	Machining range	For extra finishing	For finishing	For finishing (Soft steel)	For finishing (Wiper)	For semi- finishing	For semi- finishing(Wiper)	For light roughing	For heavy roughing

Comparison table for turning insert chipbreaker

Negative inserts

180	Machining range	ZCC.CT	ZCC.CT SANDVIK KORLOY TaeguTec	KORLOY	TaeguTec	WALTER	SECO	MITSUBISHI		SUMITOMO KENNAMETAL	DIJET	НІТАСНІ	HITACHI TUNGALOY	KYOCERA VALANTTE	VALANTTE
	For finishing	EF	MF	НА	SF	NF4, FM5	MF1	SH, LM	SU, EF	FP, LF %		MP, AB BH	SS	MQ	F1, F2(2B), F5(5C)
\geq	For semi- finishing	⊠ ⊟	MM, QM XM, X	Š	ML, EM MM, VF	MM5 RM5 NM4	MF4	MS, ES GM, MM MA	EX, EG UP, GU HM	Δ	SF, SG SZ	DE SE AH	SF, SA, SM, S	MS, MU SU, HU, ST, TK	F3, F4(8A), M2(2C), M3 M4, M5(5B), M6, M7, 55, M8
	For roughing	П	MR	GS, HM	TM	NR4 NR5	M5, MR7 RR6	GH, HZ RM, HL	EM, MU MP	UP		AE	TH, SH		R3, R4, R6(9A) R7(9B), R9(9C)
	For finishing	PM	ΑF			MK5	MF2, M3 MF5, M4	VA AH		Z		VA, AH	CF	ΚQ	F2(2B)
*	For Semi- Finishing	A	Ϋ́M	Through chip- breaker, HM	MC	RK5 NM5	M5	V AE	UZ, GZ UX	RP, UN	PG	V, AE	OM	KG, C	M5(5B), M6, M8
	For roughing	Without chip- breaker	KR	GR, HR GH	Ā	RK7		RE			99	RE		KH, GC	R3, R4, R7(9B)
	For finishing	NF/NGF	SF SGF		EA	NF4, NFT MS3	MF5, MF1 MF4	FJ*, LS MJ, MJ*	EF, SU%	FS, LF ** MS			HRF	Ø	F5(5C), M2(2C)
G	For semi- finishing	ΣZ	NGP‰, SM			NMT, NMS	M1	MS	EG, EX SU※, UP	NGP %		5	HRM, SA HMM	SQ, MS MU, TK	M4, M5(5B), M7, 55
	For roughing	SNR	SMR		ET	NRS	MR3 MR4	GJ	MU	RP				SG	

Comparison table for turning inserts chipbreaker

OSI	Machining range	ZCC.CT	SANDVIK	KORLOY	TaeguTec	WALTER	SECO	MITSUBISHI	SUMITOMO	KENNAMETAL	DIJET	нітасні	TUNGALOY	KYOCERA	VALANTTE
	For finishing	SF, HF XF	PF, UF XF	НБР	FA, FG FX	PF4 FP4	FF1 F1	FV, SV FP, LP	FP, LU SU, SK	11, UF LF, FP		ÖΓ	PF, PSF PS, PSS	GP, XP VF, PP	PF4 JQ, JZ
	For finishing (Wiper)		WF			PF2% PF, PF5%	W-F1	SW	RUW	WH				WP	
<u> </u>	For semi- finishing	HM, XM	UM, XM PM, PR XR	HMP C25	MT, PC	PS5 PM5 FP6	F2 MF2, M5	MV, MP	Ω	MF, MP	E	司	PM 23, 24	HQ, XQ GK MF%	PM2 PM4
	For semi- finishing (Wiper)		MM		WT	Md	W-F2 W-M3	WW		MW					
2	For finishing	Ħ	MF	HFP		FM4	F1, F2	FM, LM	FC%, SI% LU, SU	MF		ММ	PF, PSF PS, PSS	CF %, CK % GQ %, GF % MQ, SK	1A, 2A
	For semi- finishing	E	Σ N	HMP C25		MM4 RM4		MM	D N	Μ			PM	à Ã	PM2
¥	For semi- finishing	HM, HR without chip-breaker	KM KR	HMP C25		FK6	F1 M3, M5	MK Without chip- breaker	MU Without chip- breaker	Without chip- breaker			CM Without chip- breaker	Without chip- breaker **	PM2 PM4
C)	For finishing/ For semi- finishing	NGF						FS%, LS% FJ%, FS-P% LS-P%	SL*	LF %				MQ	PM2, 1A 2A
2	For general turning	H	AL	ТААК	FL	PM2, FN2 MN2	AL %	AZ%	AG	HP%	ALU ACB ASF		ALЖ	AH%	1L, 1A 2A
% Per	% Periphery grinding type) type													

Positive inserts

Comparison table for turning insert chipbreaker